

1



Right Side of Downstream Embankment Slope with Topsoil being stockpiled. Pipes shown (right side of photograph) are abandoned pipes removed from the service spillway discharge channel.

2



Debris Removal of Service Spillway Sump and 5.5' wide channel.



CHA # 30855

**Wee Wah Lake & Pond No. 3  
Dam Rehabilitation Project  
Village of Tuxedo Park, New York**

August 25, 2017

3



Outlet Valve within Service Spillway Sump.

4



Looking Upstream in Auxiliary Spillway at drilling operations for VW-Piezometer Installation.



CHA # 30855

**Wee Wah Lake & Pond No. 3  
Dam Rehabilitation Project  
Village of Tuxedo Park, New York**

August 25, 2017



5



Parapet wall footing excavation. PVC pipe is casing of VW-Piezometer EM-5.

6



Pond No. 3 stump removal and clearing and grubbing of LLO siphon trench alignment.



CHA # 30855

**Wee Wah Lake & Pond No. 3  
Dam Rehabilitation Project  
Village of Tuxedo Park, New York**

August 25, 2017