



1

Left Side of Downstream Embankment Slope with Topsoil being place adjacent to rip rap slope protection placed to edge of service spillway discharge channel.



2

Completed left downstream slope grading prior to topsoil placement. Background shows completed embankment with temporary grass growth.



CHA # 30855

**Wee Wah Lake & Pond No. 3
Dam Rehabilitation Project
Village of Tuxedo Park, New York**

September 25, 2017

3



Service Spillway showing installation of grouted dowel hooks for overpour concrete wall construction.

4



Coring operations in preparation of through bolt installations of the right auxiliary training wall.



CHA # 30855

**Wee Wah Lake & Pond No. 3
Dam Rehabilitation Project
Village of Tuxedo Park, New York**

September 25, 2017

5



Start of parapet wall base construction. Note concrete pump truck at east end of the wall.

6



View of parapet wall segments E and D from right abutment of the dam just prior to concrete placement for base construction.



CHA # 30855

**Wee Wah Lake & Pond No. 3
Dam Rehabilitation Project
Village of Tuxedo Park, New York**

September 25, 2017