

1



Completed construction of forebay structure for primary spillway and the integral segment of the parapet wall.

2



Completed reinforced concrete parapet wall with exception of Segment A on far left side.  
Photo also shows high construction water condition in front of Auxiliary spillway.



CHA # 30855

**Wee Wah Lake & Pond No. 3  
Dam Rehabilitation Project  
Village of Tuxedo Park, New York**


January 28, 2018

3



LLO pipe bulkhead with 12" dia. pipe connected and flowing full. Contractor working to open 18" dia. outlet.

4



Flow after opening 18" dia. bulkhead penetration.



CHA # 30855

**Wee Wah Lake & Pond No. 3  
Dam Rehabilitation Project  
Village of Tuxedo Park, New York**

January 28, 2018

5



Parapet wall stone effacement construction on u/s face of Segment E.

6



Primary spillway after stone/masonry removals to approximately elev. 487.5 ft. Temporary stone/masonry crest will be raised to elevation 492 ft. with the construction of a new reinforced concrete weir structure.



**Wee Wah Lake & Pond No. 3  
Dam Rehabilitation Project  
Village of Tuxedo Park, New York**