

1



Left Side of Downstream Embankment Slope Following Clearing, Grubbing and Benching.

2



Right Side of Downstream Embankment Slope Following Clearing, Grubbing and Benching.



CHA # 30855

**Wee Wah Lake & Pond No. 3  
Dam Rehabilitation Project  
Village of Tuxedo Park, New York**

July 24, 2017

3



Compacted Embankment Filled on right Downstream Slope after Sealing with Compactor ahead of rain.

2



Looking Upstream through drained Service Spillway.



CHA # 30855

**Wee Wah Lake & Pond No. 3  
Dam Rehabilitation Project  
Village of Tuxedo Park, New York**

July 24, 2017

5



Contractor Assembling Temporary Cofferdam from Service Spillway to Left Abutment.

6



Completed Temporary Cofferdam and start of Dewatering of Coffered Area.



CHA # 30855

**Wee Wah Lake & Pond No. 3  
Dam Rehabilitation Project  
Village of Tuxedo Park, New York**

July 24, 2017

7



Dewatered Coffers Area Upstream of Auxiliary Spillway.

8



Existing Geomembrane (60 mil) Seepage Barrier at base of Auxiliary Spillway.



CHA # 30855

**Wee Wah Lake & Pond No. 3  
Dam Rehabilitation Project  
Village of Tuxedo Park, New York**

July 24, 2017

9.



View of Pond No. 3 Dam Right Abutment/Embankment Contact and Primary Spillway.

10



View of Pond No. 3 at Construction Pool. Dam Repairs and Modification Anticipated for Late Summer.



CHA # 30855

**Wee Wah Lake & Pond No. 3  
Dam Rehabilitation Project  
Village of Tuxedo Park, New York**

July 24, 2017