

1



Left Side of Downstream Embankment Slope Showing completed rip rap and earth embankment. Permanent Access Road is not complete.

2



Right Side of Downstream Embankment Slope showing completed rip rap and earth embankment. Seepage collection and monitoring system is not complete along service discharge channel.



CHA # 30855

**Wee Wah Lake & Pond No. 3
Dam Rehabilitation Project
Village of Tuxedo Park, New York**

October 26, 2017

3



Capstone removal in preparation of right service spillway training wall removals for primary spillway expansion.

4



Capstone removal in preparation of auxiliary spillway crest reconstruction.



CHA # 30855

**Wee Wah Lake & Pond No. 3
Dam Rehabilitation Project
Village of Tuxedo Park, New York**

October 26, 2017

5



Remove of old concrete “capstone” for installation of new bluestone.

6



Excavation for repair auxiliary spillway floor.



CHA # 30855

**Wee Wah Lake & Pond No. 3
Dam Rehabilitation Project
Village of Tuxedo Park, New York**

October 26, 2017

7



New low level outlet pipe set and braced in service spillway.

8



Completed reinforced concrete Segments E and D of Parapet Wall ready for stone effacement construction



CHA # 30855

**Wee Wah Lake & Pond No. 3
Dam Rehabilitation Project
Village of Tuxedo Park, New York**

October 26, 2017

9.



Reinforced concrete construction for Segment B of Parapet Wall.

10



View of Pond No. 3 start of LLO siphon system construction. Photo shows valve vault set to grade near dam crest.



CHA # 30855

**Wee Wah Lake & Pond No. 3
Dam Rehabilitation Project
Village of Tuxedo Park, New York**

October 26, 2017